



Circuit Diagram




8020 Vice




8020 Vice

More Shielding Thoughts (11/19)




- 1.) Put wheels inside shielding frame ^{and} ~~to~~ have a door to open / insert insulation.

2x - Side Panels.



Place linear bearing for roller wheels in the metal part of casing frame.



SIGNATURE

DATE

Continued to page

Wiki Page Link

- [http://mindworks.shoutwiki.com/wiki/Insulation Measuring and Cutting Module](http://mindworks.shoutwiki.com/wiki/Insulation_Measuring_and_Cutting_Module)

Spring Semester Meeting Times

